

## **Letter of Recognition for Initial Findings**

The RMG Sustainability Council (RSC) hereby recognizes that:

## Sinha Knit Industries Limited (10184)

Chamurkhan, P.O-Uttarkhan, P.S- Uttara

Has successfully completed all remediation measures required from the Accord initial inspections for structural, electrical, and fire safety conducted in Apr 2014.

RSC engineers have physically verified that all initial finding items in the corrective action plan, developed from the Accord initial inspections and approved by the Accord Chief Safety Inspector, have been correctly repaired.

The Accord initial inspections covered minimum life safety issues in the areas of structural, electrical, and fire safety based on an inspection standard developed with the Government of Bangladesh, as well as national and international safety engineers through the facilitation of the ILO.

Factory is still required to complete all the findings, and the factory safety is a continuous process which requires regular monitoring, maintenance, and in-factory safety systems and practices. The RSC will continue to support the factory managers and workers in institutionalising and further advancing such culture of safety and health at the factory.

The RSC extends our congratulations to Sinha Knit Industries Limited (10184) for achieving this safety milestone.

myte - .

Iqbal M Hussain Managing Director & Acting Chief Safety Officer RMG Sustainability Council (RSC)

Date: 19/07/2021

DELIVERING WORLD-CLASS SUSTAINABLE WORKPLACE SAFETY PROGRAMMES

















<sup>&</sup>lt;sup>1</sup> This letter of recognition verifies that the factory has successfully remediated all items from the limited initial Accord inspection, and that the items in the corrective action plans were in a correct state of repair at the time of the verification inspection. This letter of recognition should not be considered to be a certification or endorsement on the part of the RMG Sustainability Council (RSC). This letter does not address new findings identified during RSC follow-up inspections conducted after the Accord initial inspections.